

DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

0001

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Inspection Report

Minerals Regulatory Program

9/19/2006

Supervisor Sw for

Mine Name: Indian Queen **Operator Name: Gary Applegate**

995 N. Main PO Box 668

Tooele, Utah 84074

Inspector(s): Tom Munson

Other Participants: Gary Applegate

Mine Status: Regraded

Permit number: M010019 Inspection Date: 08/01/2006

Time: 2:00 PM

Weather: Sunny

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	\boxtimes		
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Concurrent Reclamation	\boxtimes	\boxtimes	
7. Backfilling/Grading (trenches, pits, roads,	\square		
highwalls, shafts, drill holes)			
8. Water Impoundments			
9. Soils	\boxtimes	\boxtimes	
10. Revegetation	\boxtimes	\boxtimes	
11. Air Quality			
12. Other			

Purpose of Inspection: To determine if the site had been properly graded and the topsoil redistributed in preparation of the seeding.

Directions to Site: The site is West of Milford in the San Francisco Mountains

Inspection Summary: The site had been properly regraded. It was also determined that the operator had regraded the access road to a rough two track. All disturbance was covered with available topsoil and left sufficiently rough to allow for good seeding potential and erosion protection.

Conclusions and Recommendations: The Division recommends that the operator immediately seed the site before the topsoil crusts over. It was also recommended that he save his seed tags and present them to the division to prove what species were seeded. The operator asked for a release of the regrading money and I informed him that he needed to send in a Bond Release Form. I informed him that the surety bond that the Division currently holds is in question, because Frontier Insurance Company is not in US Treasury Circular 570 or is it A minus or better in its rating. Therefore it was recommended that he would need to replace this surety bond with an approved bond for re-reseeding costs which would be determined by the Division.

Inspector's Signature	/homas	Mu	[

Date: 9/27/06 DH:tm:pb

Operator Attachment: Photos

O:\M001-Beaver\M0010019-IndianQueen\draft\insp-08012006.doc






ACCESS TO UPPER PIT REMOSED







LOWER PAD LOOKING WEST









LOWER PAD

TOPSOIL SPREAD



SITE FROM A DISTANCE



HIGHWALL COVERED UD



LOWER PAD REGRAPED



REGEMBED TOUGE TRACK



LOWER HIGHWARE RECLAIMED









UPPER PIT REGRADED





HIGHWALL BURIES TO EXTENT POSSIBLE



07/19/2006/13:153

UPPER PIT





ACCESS TO WEST TO LOWER PAD









6000 SICCESS





LOWER PAD I MONTH BEFORE FINAL RECLAMATION







WORKING ON LOWER RAD RECLAMATION



Ine Permit Nuperator 66 ~	imber <u>m/ooi/a</u> J-Applege	objq Mine I	Vame India. Date Sent	9-26-06
CONFIDE	NTIALBON PUL DOCUMEN	D CLOSURE T TRACKING S		_EXPANDABLE APPROVED NOI
Description			YEA	R-Record Number
_NOI	_Incoming Lelease Let	XOutgoing ter 9-29	_Internal	Superceded
NOI Bono Re	_Incoming lease Find	_Outgoing	△Internal	_Superceded
NOI _/nspech	_Incoming an Report	_Outgoing	<u>N</u> Internal	Superceded
NOI	Incoming	Outgoing	Internal	Superceded
	/2 X 11 MAP I			LARGE MAP